

WHATCOM COUNTY

SITE I

ELDRIDGE MUNICIPAL LANDFILL

CleanupSite ID: **1897**

FS ID: **16195**

Alternate Name(s): ELDRIDGE MUNICIPAL LANDFILL

LOCATION:

[View Vicinity Map](#)

Address: **3100 block W Illinois**
Bellingham 98224

Lat/Long: **48.76704 -122.51156**
Township/Range/Section: **38N 2E 43**

Legislative District: **42**
Congressional District: **2**

STATUS:

[View Site Web Page](#)

Ecology Status: **Cleanup Started**
WARM BIN#:

Responsible Unit: **Northwest**
Site Manager: **O'Herron, Mary**
Statute: **MTCA**

Is Brownfield?
Environmental Covenant?
Is PSI Site? **Yes**

UST Site ID:
WRIA ID: **1**

NFA Received? NFA Date: NFA Reason:

ASSOCIATED CLEANUP UNIT(s)

culD	Cleanup Unit Name	Unit Type	Process Type	Unit Status	Size (Acres)	ERTS ID
1714	ELDRIDGE MUNICIPAL LANDFILL	Upland	Ecology-supervised or conducted	Cleanup Started		611984

SITE ACTIVITIES:

Applies to:	Related ID (Unit-LUST-VCP)	Activity Display Name	Status	Start Date	End Date	Legal Mechanism	Performed By	Project Manager
CleanupSite		Site Discovery/Release Report Received			11/9/2005			O'Herron, Mary
CleanupSite		Initial Investigation / Federal Preliminary Assessment	Completed	4/17/2009	4/17/2009		Ecology	O'Herron, Mary
CleanupSite		Early Notice Letter(s)			11/30/2009			O'Herron, Mary
CleanupSite		Order/Decree/Amendment		11/19/2010				Northwest Region
CleanupSite MilestoneTyp		Ecology Remedial Investigation and/or Feasibility Study	In Process	11/15/2010		Agreed Order	PLP	O'Herron, Mary
CleanupSite MilestoneTyp		Ecology Interim Action-Construction	Planned			Agreed Order	PLP	O'Herron, Mary

AFFECTED MEDIA & CONTAMINANTS:

Media:

Cleanup Site Details

10/29/2014

Contaminant:	Ground Water	Surface Water	Soil	Sediment	Air	Bedrock
Metals Priority Pollutants			C			
Petroleum Products-Unspecified			C			
Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level S - Suspected R - Remediated RA - Remediated-Above RB - Remediated-Below						